

Specialty Manufacturing, Inc.

Technical Bulletin

(Revised 04/02/2013)

REPLACMENT PROCEDURE:

4 AMP FUSE WITHIN 4" AND 6" TALL STROBE LIGHTS

(PART #: 515-400 AND 515-600)

This manual contains proprietary information of SMI. It is intended solely for the information and use of parties operating and maintaining the equipment described herein. Such proprietary information may not be used, reproduced, or disclosed to any other parties for any other purpose without the expressed written permission of SMI.

Controlled copies of SMI documents are maintained within SMI. Printed or electronic copies in other storage locations are uncontrolled



REPLACMENT PROCEDURE: 4 AMP FUSE WITHIN 515-400 AND 515-600

Purpose:

• This technical bulletin provides information regarding the replacement procedure for strobe lights, 515-400 and 515-600, that no longer work due to a failure of the internal 4 Amp fuse.

Notice:

 These strobe lights generate high voltage to operate the xenon bulb. To prevent the risk of electrical shock, do NOT remove the lens cover of the strobe light.

WARNING!

This unit generates and stores high voltage. High voltage may be present internal to the unit's enclosure even after the external power has been removed. To prevent any shock hazard, do not remove the lens cover or attempt to service, inspect or replace any internal components.

Tools:

- ¼" Socket
- Ratchet
- 3" Extension

Procedure: (Note: All images are of the 4" Strobe light, Part Number: 515-400)

1) Disconnect: Power source to Strobe light.

(Note: The easiest way to disconnect the power is to remove the fuse within the bus fuse box that is associated with this component on the bus.)

2) Remove: 4 mounting screws on the exterior base of the strobe light. (See figure S.1.)

Controlled copies of SMI documents are maintained within SMI. Printed or electronic copies in other storage locations are uncontrolled



REPLACMENT PROCEDURE: 4 AMP FUSE WITHIN 515-400 AND 515-600



Figure S.1: Two of the four mounting screws are not pictured, they are on the opposite side of the strobe light.

3) Remove: The strobe light from the vehicle. Leave the wires on the strobe light as long as possible for factory fault analysis.

Controlled copies of SMI documents are maintained within SMI. Printed or electronic copies in other storage locations are uncontrolled

01/07/2013 Page 2 of 4



REPLACMENT PROCEDURE: 4 AMP FUSE WITHIN 515-400 AND 515-600

Rev. Level	Rev. Date	Details		
		Page	Para.	Description of Change
А	01/04/13	ALL	ALL	INITIAL RELEASE
В	04/02/13	ALL	ALL	SAFTEY UPDATE

Specialty Manufacturing Group, Inc.

10200 Pineville Rd

Pineville, NC 28134

Toll Free 800-951-STOP (7867)

Phone 704-889-7518

Fax 704-889-2760

http://www.smiglobal.net

For Technical Support, Email: tech.support@smiglobal.net

More technical publications available at:

http://www.smiglobal.net/tech_bulletins.php

Controlled copies of SMI documents are maintained within SMI. Printed or electronic copies in other storage locations are uncontrolled

01/07/2013 Page 4 of 4